

Evita 2 dura

Technical Service Bulletin # 11

Re: Product improvement for all units before S/N ARNB-0110
(Service Pack 1)

Update: May 24, 2000

Reference Doc: IDM nos. 8 / 10.98, 11 / 02.99, 12 / 02.99, and 13 / 05.99

Reason: We have developed an upgrade kit Service Pack 1 with the following improvements:

- Improvement of the CO₂ measurement function and extension of CO₂ sensor life through a new CO₂ software version 1.13 (previous version 1.11). Note: Not all devices are affected.
- New Gold Cap capacitors for the CO₂ Carrier PCB P/N 83 06 611 up to revision level 9.1 to avoid device failure code "02.71.003 - low Gold Cap capacity".
- The kit is delivered with 2 modified Expiration Valve caps to prevent tendency of resonance vibration. Note: Not all valves are affected.
- A second loudspeaker is installed in most units starting with a S/N ARMX-YYYY (1998 production). Some users/operators complained that the audible alarms are too loud. If applicable, the second loudspeaker is to be disconnected. The cable harness with the connector must be fasten with a cable tie in such way that an electrical contact to housing or other parts is not possible.
- Modification of the CO₂ Carrier PCB with a Diode to avoid the message "Ext. batteries reversed poles" if a shortened airway temperature sensor is connected. Note: Not all devices are affected.


Solution: Installation of Kit Service Pack 1.

Devices affected: Evita 2 dura up to S/N ARNB-0109 shipped prior to March 1999. All units with a S/N starting with DRXX-YYYY are not effected.

Evita 2 dura is already modified if:

- The CO₂ Carrier PCB P/N 83 06 611 is modified with the piggy back board "SuperGold PCB". The B-side of this board is labeled with 83 09 218.

or



- The revision level of the CO₂ Carrier PCB P/N 83 06 611 is 9.2 or higher (sticker with 83 06 611 - 9.2).

When: At next Service Call or Preventive Maintenance.

Additional Info: After installation of the new CO₂ software version 1.13, older CO₂ sensor types (P/N 68 70 300) up to S/N ARMF-0296 (June 1998), are to be calibrated with test gas according to PMS procedure or Operating Instructions.

Cost: Covered by Customer post warranty

Ordering Info: Upgrade kit Service Pack 1 P/N 84 11 891

Distribution: Dräger Service Personnel and Authorized Service Organizations for CCS products.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789

Dräger Medical, Inc.
Technical Product Manager